

Direct Fix Vices Fixing Detail





into place with 1/2 nuts

Boundary joists

